

CAUTION

This vehicle is equipped with Meritor's driver-controlled, full-locking differential (DCDL).

- Engage DCDL only under poor road conditions.
- Do not engage DCDL during downhill operation.
- Do not engage DCDL or operate the vehicle at speeds above 25 mph.

When DCDL is engaged, an “understeer” condition can occur when making turns, so operate the vehicle carefully. When you disengage DCDL, normal steering resumes.

Refer to the vehicle manufacturer's manual or Meritor technical bulletin TP-9579. To obtain this bulletin, visit Literature on Demand at arvinmeritor.com or call 800-535-5560.